

Oil Field Environmental Incident Summary

Incident: 20150420131339 **Date/Time of Notice:** 04/20/2015 13:13

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: SKARDERUD 10-7

Field Name: TEMPLE

Well File #: 10073

Date Incident: 4/9/2015 **Time Incident:** 13:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 95

Sec: 7

Qtr:

Location Description:

Submitted By: Scott Hunskor

Received By:

Contact Person: Scott Hunskor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Clean out clean oil line, clean out vent pit

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 4/20/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.